BROWN, CAROLYN 36-40H2-14L



State Farm
P.O. Box 106169
Atlanta, GA 30348-6169
Fax: 1-844-236-3646
statefarmfireclaims@statefarm.com

Structural Damage Claim Policy

This estimate is priced based on estimated market pricing for the cost of materials, labor, and other factors at the time of the loss.

Adjustments in market pricing and timing of the repairs may impact the final cost of covered repairs. Should you or the contractor you select have questions concerning our estimate, please contact us. If your contractor's estimate is higher than ours, you should contact us prior to beginning repairs. State Farm will work with you and your contractor to determine the actual and necessary cost of covered repairs at the time repairs will be completed, subject to policy terms, conditions and limits.

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of the damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- Depending upon the complexity of your repair, our estimate may or may not include an allowance for general contractor's overhead and profit. If you have questions regarding general contractor's overhead and profit and whether general contractor services are appropriate for your loss, please contact your claim representative before proceeding with repairs.
- There may be building codes, ordinances, laws, or regulations that affect the repairs of your property. These items may or may not be covered by your policy. Please contact your claim representative if you have any questions regarding coverage which may be available under your policy.
- State Farm® cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of the workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you not State Farm.

If you have any questions or need additional information regarding your claim, please contact your claim representative immediately.



Building Estimate Summary Guide

This summary guide is based on a sample estimate and is provided for reference only. Please refer to the estimate for specifics of your claim.

	Sta	ite Farm Ins	surance		
Insured:	Smith, Joe & Jane		Estimate:	00-0000-00	00
Property:	1 Main Street	Claim number:	00-0000-00	00	
	Anywhere, IL 0000	0-0000	Policy Number:	00-00-0000)-0
Type of Loss:	Other		Price List:	ILBL8F_MA	AR 13
Deductible:	\$1,000.00	61,000.00			n/Service/ ed In, : Apply
	Su	mmary for	Dwelling	1	
Line Item Total	1			-	5,953.10
Material Sales Ta	ax	@	10.000% x 1,520.0	0	AI
Subtotal				7	6,105.10
General Contract	tor Overhead 2	@	10.0% x 6,105.1	0	610.51
General Contract	0				
Replacement Co	st Value (Including 0	General Contrac	tor Overhead and Prof	it 3	7,326.12
Less Depreciatio	n (Including Taxes)	4			(832.50)
Less General Co	ntractor Overhead &	Recov	verable &		
Non - recoverabl	e Depreciation				(166.50)
Less Deductible	5	7			
Net Actual Cash	Value Payment 6				
			(
IVIax	imum Additio	nai Amoun	ts Available If I	ncurrea:	
Total Line Item D	epreciation (Includin	g Taxes) 4	832.5	0	
_ess Non - recov	erable Depreciation	(Including Taxes	s) [7]		
Subtotal				312.50)
General Contrac	tor O&P on Deprecia	ation	166.5	0	
Less General Co	ntractor O&P on No	n - recoverable l	Depreciation		
Subtotal					
Total Maximum A	Additional Amounts A	Available If Incur	red 8		_
Total Amount of	Claim If Incurred 9]			
.		_			
Claim Represent					
STIMILOMA LIA	DAVABLE ADE SU	D IECT TO THE	TERMS CONDITION	IC VND I IM	ITC OF

- 1. Line Item Total Total value of all line items in the estimate plus possible adjustments for labor minimums. Labor Minimum is to cover a certain minimum number of hours for drive-time, set up time and applicable administrative costs and repairs.
- 2. General Contractor's Overhead and Profit - General contractor's charge for coordinating your repairs.
- 3. Replacement Cost Value (RCV) -Estimated cost to repair or replace damaged property.
- 4. Depreciation The decrease in the value of property over a period of time due to wear, tear, condition, and obsolescence. A portion or all of this amount may be eligible for replacement cost benefits.
- 5. Deductible The insurer will pay for losses, up to the policy limits, in excess of your applicable deductible.
- 6. Net Actual Cash Value Payment (ACV) - The repair or replacement cost of the damaged part of the property less depreciation and deductible.
- 7. Non Recoverable Depreciation -Depreciation applied to items that are not eligible for replacement cost benefits.
- 8. Total Maximum Additional Amount if Incurred - Total amount of recoverable depreciation after actual repair or replacement of the property.
- 9. Total Amount of Claim if Incurred -Total amount of the claim, including net actual cash value payment and total maximum additional amount available if incurred.

1002989 Date:

YOUR POLICY.

10/19/2022 12:34 PM Page: 2

BROWN, CAROLYN 36-40H2-14L

Insured: BROWN, CAROLYN Estimate: 36-40H2-14L
Property: 9920 HUNTERS RUN Claim Number: 3640H214L
MIDWEST CITY, OK 73130-4524 Policy Number: 36CBB9299

Home: 405-688-5934 Price List: OKOC28_OCT21

Cellular: 405-476-9198 Restoration/Service/Remodel

Type of Loss: Hail
Deductible: \$2,040.00
Date of Loss: 10/14/2021
Date Inspected: 10/19/2022

Summary for Coverage A - Dwelling - 35 Windstorm and Hail

Line Item Total	18,639.40
Material Sales Tax	605.97
Replacement Cost Value	19,245.37
Less Depreciation (Including Taxes)	(5,696.41)
Less Deductible	(2,040.00)
Net Actual Cash Value Payment	\$11,508.96

Maximum Additional Amounts Available If Incurred:

Total Line Item Depreciation (Including Taxes)	5,696.41
Replacement Cost Benefits	5,696.41
Total Maximum Additional Amount Available If Incurred	5,696.41
Total Amount of Claim If Incurred	\$17,205.37

Norton, Joshua 844

844-458-4300

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.



Case 5:22-cv-00971-R Document 1-5 Filed 11/10/22 Page 4 of 12

Explanation of Building Replacement Cost Benefits Homeowner Policy

Coverage A - Dwelling - 35 Windstorm and Hail

To: Name: BROWN, CAROLYN

Address: 9920 HUNTERS RUN

City: MIDWEST CITY State/Zip: OK, 73130-4524

Insured: BROWN, CAROLYN Claim Number: 3640H214L

Date of Loss: 10/14/2021 Cause of Loss: HAIL

Your insurance policy provides replacement cost benefits for some or all of the loss or damage to your dwelling or structures. Replacement cost benefits pays the actual and necessary cost of repair or replacement, without a deduction for depreciation, subject to your policy's limit of liability. To receive replacement cost benefits you must:

- 1. Complete the actual repair or replacement of the damaged part of the property within two years of the date of loss;
- 2. Promptly notify us within 30 days after the work has been completed; and
- 3. Confirm completion of repair or replacement, by submitting invoices, receipts or other documentation to your agent or claim office.

Until these requirements have been satisfied, our payment(s) to you will be for the actual cash value of the damaged part of the property, which may include a deduction for depreciation.

Without waiving the above requirements, we will consider paying replacement cost benefits prior to actual repair or replacement if we determine repair or replacement costs will be incurred because repairs are substantially under way or you present a signed contract acceptable to us.

The estimate to repair or replace your damaged property is \$19,245.37. The enclosed claim payment to you of \$11,508.96 is for the actual cash value of the damaged property at the time of loss, less any deductible that may apply. We determined the actual cash value by deducting depreciation from the estimated repair or replacement cost. Our estimate details the depreciation applied to your loss. Based on our estimate, the additional amount available to you for replacement cost benefits (recoverable depreciation) is \$5,696.41.


If you cannot have the repairs completed for the repair/replacement cost estimated, please contact your claim specialist prior to beginning repairs.

All policy provisions apply to your claim.

Date: 10/19/2022 12:34 PM FC0006615 10/22/2020 Page: 4

BROWN, CAROLYN 36-40H2-14L

Source - Eagle View Source - Eagle View



Dwelling Roof

3,419.54 Surface Area259.18 Total Perimeter Length106.92 Total Hip Length

34.20 Number of Squares70.23 Total Ridge Length

QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Tear off, haul and dispose of comp	. shingles - Laminated					
34.20 SQ	52.20	0.00	1,785.24			1,785.24
Laminated - comp. shingle rfg wa	/ felt					
38.67 SQ	241.67	396.45	9,741.83	11/30 yrs	(3,572.01)	6,169.82
				Avg.	36.67%	
Remove Additional charge for stee	p roof - 7/12 to 9/12 slo	pe				
34.20 SQ	12.65	0.00	432.63			432.63
Additional charge for steep roof - 7	7/12 to 9/12 slope					
38.66 SQ	39.27	0.00	1,518.18			1,518.18
Ridge cap - composition shingles						
178.00 LF	3.84	18.47	701.99	11/25 yrs	(308.88)	393.11
				Avg.	44.00%	
Asphalt starter - universal starter co	ourse					
260.00 LF	1.72	11.59	458.79	11/20 yrs	(252.33)	206.46
				Avg.	55.00%	
Gable cornice return - laminated				_		
5.00 EA	69.07	3.02	348.37	11/30 yrs	(127.74)	220.63
				Avg.	36.67%	
Roof vent - turbine type						
2.00 EA	110.17	11.88	232.22	11/35 yrs	(72.98)	159.24
				Avg.	31.43%	
R&R Rain cap - 4" to 5"				C		
3.00 EA	35.67	4.24	111.25	11/35 yrs	(34.96)	76.29
				Avg.	31.43%	
Flashing - pipe jack				Ç		
3.00 EA	41.92	3.79	129.55	11/35 yrs	(40.71)	88.84
2.00 2.1		5>	123.00	Avg.	31.43%	00.01
* Flashing - pipe jack				8	31.1370	
3.00 EA	77.67	12.68	245.69	11/35 yrs	(77.22)	168.47
3.00 221	77.07	12.00	213.05	Avg.	31.43%	100.17
Digital satellite system - Detach &	reset			11,6.	31.4370	
1.00 EA	36.35	0.00	36.35			36.35
Chimney flashing - average (32" x		0.00	50.55			50.55
1.00 EA	354.25	7.32	361.57	11/35 yrs	(113.64)	247.93
1.00 EA	337.43	1.52	301.37	Avg.	31.43%	∠ + 1.33
				1116.	J1. 4 J/0	

BROWN, CAROLYN 36-40H2-14L

CONTINUED - Dwelling Roof

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
CODES:							
Drip edge							
	260.00 LF			_		WHEN	INCURRED
	code upgrade item i DEdge @ \$2.43 per B - 1/2"		y repaired or replac	ed.			
	3,419.54 SF					WHEN	INCURRED
	code upgrade item i OSB 1/2@\$2.32 Si et - 26 to 50 SF		y repaired or replac	ed.			
	1.00 EA					WHEN	INCURRED
The following of Cricket 26-508	code upgrade item i SF \$257.42	is paid when actuall	y repaired or replac	ed.			
Totals: Dwelli	ing Roof		469.44	16,103.66		4,600.47	11,503.19
Area Totals: So	ource - Eagle View						
2	224.42 Exterior Wa	ll Area					
3,4	119.54 Surface Area	a	34.20 Number	of Squares	259.1	8 Total Perime	ter Length
	70.23 Total Ridge	Length	106.92 Total Hij	Length			
Total: Source	- Eagle View		469.44	16,103.66		4,600.47	11,503.19
Front Elevation	n						
	0.00 SF Walls		0.00 SF Ceili	ing	0.00	SF Walls & C	eiling
	0.00 SF Floor		0.00 SF Shor	t Wall	0.00	LF Floor Peri	meter
	0.00 SF Long W	all			0.00	LF Ceil. Perin	neter
	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* R&R Gutter							
	34.33 LF	8.55	11.59	305.11	11/25 yrs Avg.	(134.25) 44.00%	170.86
* Downspout -	aluminum - up to 5'						
	24.00 LF	8.09	8.10	202.26	11/25 yrs Avg.	(88.99) 44.00%	113.27
D 0 D 1111 1	4 0 00						

2.85

11/30 yrs

Avg.

26.29

(15.20)

36.67%

41.49

R&R Window screen, 1 - 9 SF

1.00 EA

R&R Overhead door & hardware - 16' x 7' - Standard grade

38.64

BROWN, CAROLYN 36-40H2-14L

CONTINUED - Front Elevation

	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Totals: Front	Elevation		93.88	1,705.39		601.92	1,103.47
Right Elevation	n						
	0.00 SF Walls		0.00 SF Ceiling	g	0.00	SF Walls & Ce	iling
	0.00 SF Floor		0.00 SF Short V			LF Floor Perim	_
	0.00 SF Long W	all			0.00	LF Ceil. Perim	eter
	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* R&R Gutter	63.33 LF	8.55	21.38	562.85	11/25 yrs Avg.	(247.66) 44.00%	315.19
Totals: Right l	Elevation		21.38	562.85		247.66	315.19
Rear Elevation	0.00 SF Walls 0.00 SF Floor		0.00 SF Ceiling 0.00 SF Short V			SF Walls & Ce LF Floor Perim	_
	0.00 SF Long W	all			0.00	LF Ceil. Perim	eter
	QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* R&R Downsp	oout - aluminum - up 16.00 LF	8.55	5.40	142.20	11/25 yrs Avg.	(62.57) 44.00%	79.63
Totals: Rear E	Elevation		5.40	142.20		62.57	79.63
Left Elevation							
	0.00 SF Walls		0.00 SF Ceiling	5	0.00	SF Walls & Ce	iling
	0.00 SF Floor		0.00 SF Short V			LF Floor Perim	_
	0.00 SF Long W	all			0.00	LF Ceil. Perim	eter

		State Farm				
ROWN, CAROLYN						36-40H2-14
QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
* R&R Gutter						
47.00 LF	8.55	15.87	417.72	11/25 yrs	(183.79)	233.93
				Avg.	44.00%	
Totals: Left Elevation		15.87	417.72		183.79	233.93
Debris Removal						
0.00 SF Walls		0.00 SF Ceilin	g	0.00	SF Walls & C	eiling
0.00 SF Floor		0.00 SF Short	Wall	0.00	LF Floor Peri	meter
0.00 SF Long Wa	ıll			0.00	LF Ceil. Perir	neter
QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Haul debris - per pickup truck load -	- including dump fe	ees				
1.00 EA For non roofing material	137.72	0.00	137.72			137.72
Totals: Debris Removal		0.00	137.72		0.00	137.72
Area Totals: Source - Eagle View						
224.42 Exterior Wall	Area					
3,419.54 Surface Area		34.20 Number of	Squares	259.1	8 Total Perime	ter Length
70.23 Total Ridge I	ength	106.92 Total Hip	Length			
Total: Source - Eagle View		605.97	19,069.54		5,696.41	13,373.13
Labor Minimums Applied						
QUANTITY	UNIT PRICE	TAX	RCV	AGE/LIFE CONDITION	DEPREC. DEP %	ACV
Window labor minimum						
1.00 EA	175.83	0.00	175.83			175.83
Totals: Labor Minimums Applied	ì	0.00	175.83		0.00	175.83

Date: 10/19/2022 12:34 PM Page: 8

605.97

19,245.37

5,696.41

13,548.96

Line Item Totals: 36-40H2-14L

Case 5:22-cv-00971-R Document 1-5 Filed 11/10/22 Page 9 of 12

State Farm

BROWN, CAROLYN 36-40H2-14L

Grand Total Areas:

224.42 Exterior Wall Area

3,419.54 Surface Area 70.23 Total Ridge Length 34.20 Number of Squares106.92 Total Hip Length

259.18 Total Perimeter Length

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION	LINE ITEM QTY	REPL. COST TOTAL	ACV	NON-REC. DEPREC.	MAX ADDL. AMT AVAIL.
DMO GENERAL DEMOLITION					
Haul debris - per pickup truck load -	1.00 EA	\$137.72	\$137.72	\$0.00	\$0.00
including dump fees TOTAL GENERAL DEMOLITION		\$137.72	\$137.72	\$0.00	\$0.00
		Ψ137.72	ΨΙΟΙΙΙ	Ψ0.00	Ψ0.00
DOR DOORS					
R&R Overhead door & hardware - 16' x 7' Standard grade	- 1.00 EA	\$1,156.53	\$793.05	\$0.00	\$363.48
TOTAL DOORS		\$1,156.53	\$793.05	\$0.00	\$363.48
FRM FRAMING & ROUGH CARPE	NTRY				
Saddle or cricket - 26 to 50 SF TOTAL FRAMING & ROUGH CARPE	1.00 EA	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
RFG ROOFING					
Laminated - comp. shingle rfg w/ felt	38.67 SQ	\$9,741.83	\$6,169.82	\$0.00	\$3,572.01
Tear off, haul and dispose of comp. shingles - Laminated	34.20 SQ	\$1,785.24	\$1,785.24	\$0.00	\$0.00
Asphalt starter - universal starter course	260.00 LF	\$458.79	\$206.46	\$0.00	\$252.33
Digital satellite system - Detach & reset	1.00 EA	\$36.35	\$36.35	\$0.00	\$0.00
Drip edge	260.00 LF	\$0.00	\$0.00	\$0.00	\$0.00
Chimney flashing - average (32" x 36")	1.00 EA	\$361.57	\$247.93	\$0.00	\$113.64
Flashing - pipe jack	3.00 EA	\$129.55	\$88.84	\$0.00	\$40.71
Flashing - pipe jack	3.00 EA	\$245.69	\$168.47	\$0.00	\$77.22
Gable cornice return - laminated	5.00 EA	\$348.37	\$220.63	\$0.00	\$127.74
Ridge cap - composition shingles	178.00 LF	\$701.99	\$393.11	\$0.00	\$308.88
Sheathing - OSB - 1/2"	3,419.54 SF	\$0.00	\$0.00	\$0.00	\$0.00
Additional charge for steep roof - 7/12 to 9/12 slope	38.66 SQ	\$1,518.18	\$1,518.18	\$0.00	\$0.00
Remove Additional charge for steep roof - 7/12 to 9/12 slope	34.20 SQ	\$432.63	\$432.63	\$0.00	\$0.00
Roof vent - turbine type	2.00 EA	\$232.22	\$159.24	\$0.00	\$72.98
R&R Rain cap - 4" to 5"	3.00 EA	\$111.25	\$76.29	\$0.00	\$34.96
TOTAL ROOFING		\$16,103.66	\$11,503.19	\$0.00	\$4,600.47
SFG SOFFIT, FASCIA, & GUTTER					
R&R Downspout - aluminum - up to 5"	16.00 LF	\$142.20	\$79.63	\$0.00	\$62.57
R&R Gutter	144.66 LF	\$1,285.68	\$719.98	\$0.00	\$565.70
Downspout - aluminum - up to 5" TOTAL SOFFIT, FASCIA, & GUTTER	24.00 LF	\$202.26 \$1,630.14	\$113.27 \$912.88	\$0.00 \$0.00	\$88.99 \$717.26

Note: Slight variances may be found within report sections due to rounding

Case 5:22-cv-00971-R Document 1-5 Filed 11/10/22 Page 11 of 12

Trade Summary

Includes all applicable Tax, General Contractor O&P, and Labor Minimums

DESCRIPTION	LINE ITEM QTY	REPL. COST TOTAL	ACV	NON-REC. DEPREC.	MAX ADDL. AMT AVAIL.
WDR WINDOW REGLAZING & RE	EPAIR				
R&R Window screen, 1 - 9 SF	1.00 EA	\$41.49	\$26.29	\$0.00	\$15.20
TOTAL WINDOW REGLAZING & RE	PAIR	\$41.49	\$26.29	\$0.00	\$15.20
WDW WINDOWS - WOOD					
Window labor minimum	1.00 EA	\$175.83	\$175.83	\$0.00	\$0.00
TOTAL WINDOWS - WOOD		\$175.83	\$175.83	\$0.00	\$0.00
TOTALS		\$19,245.37	\$13,548.96	\$0.00	\$5,696.41

Note: Slight variances may be found within report sections due to rounding



Source - Eagle View